

CLEANING LABORATORY EVALUATION SUMMARY

SCL #: 2008

DateRun: 10/07/2008

Experimenters: Heidi Wilcox

ClientType: Tool Manufacturer

ProjectNumber: Project #1

Substrates: Steel

PartType: Part

Contaminants: Metal fines

Cleaning Methods: Immersion/Soak

Analytical Methods: Visual

Purpose: To evaluate selected products on customer supplied parts using immersion cleaning at room temp.

Experimental Procedure: Eight products were selected from the lab's on-line database, www.cleansolutions.org, based on supplied information from client. Two products were diluted to 5% using DI water in 600 ml glass beakers. Six products were used at full strength. Solutions were used at room temperature, 68 F, and cleaned by immersion for 1-2 minutes and dried using air blow off for 30 seconds at room temperature.

Results: All the products seemed to remove some of the metal shot from the parts and could be seen at the bottom of the beakers. Half of the cleaners seemed to leave the parts darker then when they were cleaned and left a residue on the parts even after blow drying. Not sure if this residue will affect the copper sulfate process that is done after. The customer will be inspecting and coating the parts to see.

| Cleaner | Observation |
|------------------------|--|
| Polyspray Jet 790 XS | Iron shot on bottom of beaker. Parts dried well but were spotty. No visual residue on the parts. Tops were light in color like before they were cleaned. |
| Daraclean 282 GF | Iron shot on bottom of beaker. Parts dried well but were spotty. No visual residue on the parts. Tops were light in color like before they were cleaned. Cleaner foamed |
| Smart Solv 605 | Iron shot on bottom of beaker. Tops of parts were glossy and dark and clearly had a film or residue on them. |
| SoyClear 1500 | Iron shot on bottom of beaker. Tops of parts were glossy and dark and clearly had a film or residue on them. |
| SC Maxisolv | Iron shot on bottom of beaker. Tops of parts lighter and less residue on the parts overall |
| SolSafe 245 | Iron shot on bottom of beaker. Tops of parts lighter and less residue on the parts overall then previous two and next cleaner. |
| Bio Gold Parts Cleaner | Iron shot on bottom of beaker. Tops of parts were glossy and dark and clearly had a film or residue on them. |
| SC Soyester | Iron shot on bottom of beaker. Parts are comparable to parts cleaned in SolSafe 245. The tops were lighter and had less residue on them overall then some of the other solvents. |

Summary:

| | |
|----------------------|-------------|
| Substrates: | Steel |
| Contaminants: | Metal fines |

CLEANING LABORATORY EVALUATION SUMMARY

| Company Name: | Product Name: | Conc.: | Efficiency: | Effective: | Observations: |
|-----------------------------------|--------------------------|--------|-------------|-------------------------------------|---------------|
| US Polychem Corporation | Polyspray Jet 790 XS | 5 | | <input checked="" type="checkbox"/> | |
| Magnaflux | Daraclean 282 GF | 5 | | <input checked="" type="checkbox"/> | |
| United Laboratories International | Smart Solve 605 | 100 | | <input checked="" type="checkbox"/> | |
| AG Environmental Products | Soy Clear 1500 | 100 | | <input checked="" type="checkbox"/> | |
| Gemtek Products | Safe Care (SC) Maxi Solv | 100 | | <input checked="" type="checkbox"/> | |
| Bio Chem Systems | Solsafe 245 | 100 | | <input checked="" type="checkbox"/> | |
| Vertec BioSolvents | VertecBio Gold 35 | 100 | | <input checked="" type="checkbox"/> | |
| Gemtek Products | SC Soyester | 100 | | <input checked="" type="checkbox"/> | |

Conclusion:

The eight products removed iron shot from the parts. The issue will be the residue left on the part and if they can be copper sulfated or not. The parts will be brought down or shipped to the customer for them to try coating them and their feedback will guide the next steps on if a rinse will be tried or ultrasonics will be used.